



Fixed-wing Flying Complaints – Jan 2022

| Reference | Date/Time | Location | Runway | F/W Movements | Total Movements | Complaint | Action |
|-----------|-----------------------|----------|--------|---------------|-----------------|--|--|
| FW2022/1 | 21.02.2022 1115hrs | RH1 6DS | 25 | 128 | 166 | Complainant resides in Lodge Lane and reported fixed-wing aircraft were drifting south of the climb-out instead of maintaining a track straight ahead from Rwy 25. | Complainant spoken with by SATCO who agreed to monitor tracks of departing aircraft. |



Helicopter Flying Complaints - Jan 2022

Nil

Unlicensed Runway 07/25
Fixed-wing Visual Circuit Pattern
Maximum Circuit Altitude 1200' QNH
ATIS: Redhill Information 125.305
ATC: Redhill Tower 119.605

Redhill ATZ/LFA



Gatwick CTA
Class D
1500' 2900' ALT

Gatwick CTR
Class D
Slc - 2500' ALT