




Helicopter Flying Complaints - May 2026

Reference	Date	Location	FATO	Heli Movements	Total Movements	Complaint	Action
H2/2026	20/05/26 0001hrs	RH1 6DF	N/A	N/A	N/A	Helicopter going round in circles.	<p>The complainant resides close to Redhill Town Centre.</p> <p>The complaint relates to activity outside ATC hours. Flight tracking data showed NPAS helicopter operating in the area at the time of the complaint.</p> <p>NPAS operational flight – NFA. Complainant updated by email.</p>

Reference	Date/Time	Location	Runway	F/W Movements	Total Movements	Complaint	Action
FW7/2026	25/05/26 1244hrs	RH1 5PD	07R	155	179	Fixed-wing aircraft flew over residential property.	<p>Complainant resides within the ATZ adjacent to the climb-out and crosswind of Rwy07.</p> <p>Aircraft are required to fly south and east of this location. The aircraft was identified as an aircraft operated by Redhill Aviation. Email sent to the operator with a request for the pilot to be re-briefed.</p> <p>Screenshot attached.</p> <p>Complainant updated via email</p>
FW8/2026	25/05/26 1823, 1837 and 1836hrs	Not Given	07R	155	179	Fixed-wing aircraft flew over residential property.	<p>Complainant stated that the DA40 flying circuits was below the CAA altitude for flying over built up areas.</p> <p>The Redhill FID, used by the SATCO for evaluation purposes, showed the aircraft at 1200ft QNH 1029hPa (correct altitude). A commercial flight following app was viewed; this showed 800ft on 1013hPa.</p> <p>It showed the aircraft flying the correct circuit pattern.</p> <p>Screenshots taken, copies attached, and sent to complainant. They refused to accept this evidence. No further action.</p>

Screenshot FW7/2026



Screenshots FW8/2026

